

MO 580-1468 (2-08)

MISSOURI DEPARTMENT OF HEALTH AND SENIOR SERVICES \cdot STATE PUBLIC HEALTH LABORATORY BREATH ALCOHOL PROGRAM DATAMASTER MAINTENANCE REPORT

RECEIVED

	By Carol Day at 9:36 am, Apr 10, 2014
Complete this report at the time of the regular monthly prevent Complete this report whenever the instrument is serviced or re Retain the original and send a copy within 15 days to the Breat	ve maintenance check (not to exceed 35 days).
204073 MSHP	DATE OF INSPECTION 3/30/14
DALIAS CO. JAIL, 204 S. POPLAR BU	TIME OF INSPECTION
CHECKLIST: Place a mark in the box by each item if found to be where determined.) Unmarked items must be corrected before	esticionary or if apprehimentally and the second
DIAGNOSTIC CHECK (PRINTOUT ATTACHED)	DATE AND TIME (from printout) 3/30/14/
☐ COMPUTER	D'ETECTOR .
PROGRAM	D'FILTERS
PHEATERS SAMPLE CHAMBER 50 ℃	QUARTZ STANDARD
PFLOW DETECTOR	Q CALIBRATION
PUMP HIGH SPEED	DPRINTER
INDICATOR LIGHTS	
SIMULATOR SOLUTION SUPPLIER GUTH LABS	LOT# 13280 EXP. DATE 10/16/15
SIMULATOR TEMP (34°C ± 0.2°C) 34.08 °C	77. 47.0
	SIMULATOR SN G6755 EXP. DATE 8/8/14
CALIBRATION CHECK - (ONLY ONE STANDARD IS TO BE Run three tests using a standard solution. All three tests musi less. Mark the box corresponding to the standard solution bein 0.100% STANDARD - MUST READ BETWEEN 0.076% AN	USED PER MAINTENANCE REPORT) It be within ±5% of the standard value and must have a spread or used. (PRINTOUT ATTACHED) ID 0.105% INCLUSIVE
CALIBRATION CHECK - (ONLY ONE STANDARD IS TO BE Run three tests using a standard solution. All three tests must less. Mark the box corresponding to the standard solution being 0.100% STANDARD - MUST READ BETWEEN 0.095% AND 0.080% STANDARD - MUST READ BETWEEN 0.076% AND 0.040% STANDARD - MUST READ BETWEEN 0.038% AND 0.040% STANDARD - MUST READ BETWEEN 0.058% ST	USED PER MAINTENANCE REPORT) It be within ±5% of the standard value and must have a spread or used. (PRINTOUT ATTACHED) ID 0.105% INCLUSIVE ID 0.084% INCLUSIVE ID 0.042% INCLUSIVE
CALIBRATION CHECK - (ONLY ONE STANDARD IS TO BE Run three tests using a standard solution. All three tests mus less. Mark the box corresponding to the standard solution bein 0.100% STANDARD - MUST READ BETWEEN 0.095% AN 0.080% STANDARD - MUST READ BETWEEN 0.038% AN	USED PER MAINTENANCE REPORT) It be within ±5% of the standard value and must have a spread or used. (PRINTOUT ATTACHED) ID 0.105% INCLUSIVE ID 0.084% INCLUSIVE ID 0.042% INCLUSIVE
CALIBRATION CHECK - (ONLY ONE STANDARD IS TO BE Run three tests using a standard solution. All three tests muss less. Mark the box corresponding to the standard solution beint 0.100% STANDARD - MUST READ BETWEEN 0.095% AN 0.080% STANDARD - MUST READ BETWEEN 0.076% AN 0.040% STANDARD - MUST READ BETWEEN 0.038% AN ST 1	USED PER MAINTENANCE REPORT) It be within ±5% of the standard value and must have a spread or used. (PRINTOUT ATTACHED) ID 0.105% INCLUSIVE ID 0.084% INCLUSIVE ID 0.042% INCLUSIVE TEST 3 - 099
CALIBRATION CHECK - (ONLY ONE STANDARD IS TO BE Run three tests using a standard solution. All three tests muss less. Mark the box corresponding to the standard solution beint 0.100% STANDARD - MUST READ BETWEEN 0.095% AN 0.080% STANDARD - MUST READ BETWEEN 0.076% AN 0.040% STANDARD - MUST READ BETWEEN 0.038% AN ST 1 - 098 PERFORM R.F.L. TEST (PRINTOUT ATTACHED) ICATE THE NUMBER OF BREATH TESTS IN THE FOLLOWS NOT INCLUDE SELF-ADMINISTERED TESTS)	USED PER MAINTENANCE REPORT) It be within ±5% of the standard value and must have a spread or used. (PRINTOUT ATTACHED) ID 0.105% INCLUSIVE ID 0.042% INCLUSIVE ID 0.042% INCLUSIVE TEST 3 - 099 ING RANGES SINCE THE LAST MAINTENANCE REPORT: (.1014)
CALIBRATION CHECK - (ONLY ONE STANDARD IS TO BE Run three tests using a standard solution. All three tests muss less. Mark the box corresponding to the standard solution bein 0.100% STANDARD - MUST READ BETWEEN 0.095% AN 0.080% STANDARD - MUST READ BETWEEN 0.076% AN 0.040% STANDARD - MUST READ BETWEEN 0.038% AN ST 1 - 098 TEST 2 - 099 PERFORM R.F.I. TEST (PRINTOUT ATTACHED) INCATE THE NUMBER OF BREATH TESTS IN THE FOLLOWN ONOT INCLUDE SELF-ADMINISTERED TESTS) FUSALS (004) WITHEW NAMES AND DESCRIPE ANY ALTERATION OR MODIFICATION THAT WAS MADE OTHER SIDE IF HECESSARY).	USED PER MAINTENANCE REPORT) It be within ±5% of the standard value and must have a spread or used. (PRINTOUT ATTACHED) ID 0.105% INCLUSIVE ID 0.042% INCLUSIVE ID 0.042% INCLUSIVE TEST 3 - 099 ING RANGES SINCE THE LAST MAINTENANCE REPORT:
CALIBRATION CHECK - (ONLY ONE STANDARD IS TO BE Run three tests using a standard solution. All three tests must less. Mark the box corresponding to the standard solution bein 0.100% STANDARD - MUST READ BETWEEN 0.095% AN 0.080% STANDARD - MUST READ BETWEEN 0.076% AN 0.040% STANDARD - MUST READ BETWEEN 0.038% AN ST 1 - 098 TEST 2 - 099 PERFORM R.F.I. TEST (PRINTOUT ATTACHED) NCATE THE NUMBER OF BREATH TESTS IN THE FOLLOWN NOT INCLUDE SELF-ADMINISTERED TESTS) FUSALS (004) (00509) NITHEN NAMES AND DESCRIBE ANY ALTERATION OR MODIFICATION THAT WAS MADE OTHER SIDE IF HECESSARY).	USED PER MAINTENANCE REPORT) It be within ±5% of the standard value and must have a spread or used. (PRINTOUT ATTACHED) ID 0.105% INCLUSIVE ID 0.042% INCLUSIVE ID 0.042% INCLUSIVE TEST 3 - 099 ING RANGES SINCE THE LAST MAINTENANCE REPORT: (.1014)
CALIBRATION CHECK - (ONLY ONE STANDARD IS TO BE Run three tests using a standard solution. All three tests muss less. Mark the box corresponding to the standard solution beint 0.100% STANDARD - MUST READ BETWEEN 0.095% AN 0.080% STANDARD - MUST READ BETWEEN 0.076% AN 0.040% STANDARD - MUST READ BETWEEN 0.038% AN ST 1 - 098 PERFORM R.F.I. TEST (PRINTOUT ATTACHED) ICATE THE NUMBER OF BREATH TESTS IN THE FOLLOWN NOT INCLUDE SELF-ADMINISTERED TESTS) PUSALS (004) WITHER MARTS AND DESCRIPE ANY ALTERATION OR MODIFICATION THAT WAS MADE OTHER SIDE IF NECESSARY).	USED PER MAINTENANCE REPORT) It be within ±5% of the standard value and must have a spread or used. (PRINTOUT ATTACHED) ID 0.105% INCLUSIVE ID 0.042% INCLUSIVE ID 0.042% INCLUSIVE TEST 3 - 099 ING RANGES SINCE THE LAST MAINTENANCE REPORT: (.1014)
CALIBRATION CHECK - (ONLY ONE STANDARD IS TO BE Run three tests using a standard solution. All three tests muss less. Mark the box corresponding to the standard solution beint 0.100% STANDARD - MUST READ BETWEEN 0.095% AN 0.080% STANDARD - MUST READ BETWEEN 0.076% AN 0.040% STANDARD - MUST READ BETWEEN 0.038% AN ST 1 - 098 PERFORM R.F.I. TEST (PRINTOUT ATTACHED) ICATE THE NUMBER OF BREATH TESTS IN THE FOLLOWS NOT INCLUDE SELF-ADMINISTERED TESTS) FUSALS 6 (004) 6 (.0509) INTERNAL SHOP DESCRIPE ANY ALTERATION OR MODIFICATION THAT WAS MADE OTHER SIDE IF HECESSARY).	USED PER MAINTENANCE REPORT) It be within ±5% of the standard value and must have a spread of used. (PRINTOUT ATTACHED) ID 0.105% INCLUSIVE ID 0.084% INCLUSIVE ID 0.042% INCLUSIVE ID 0.042% INCLUSIVE TEST 3 - 099 ING RANGES SINCE THE LAST MAINTENANCE REPORT: (.1014)
CALIBRATION CHECK - (ONLY ONE STANDARD IS TO BE Run three tests using a standard solution. All three tests muss less. Mark the box corresponding to the standard solution bein 0.100% STANDARD - MUST READ BETWEEN 0.095% AN 0.080% STANDARD - MUST READ BETWEEN 0.076% AN 0.040% STANDARD - MUST READ BETWEEN 0.038% AN ST 1 - 098 TEST 2 - 099 PERFORM R.F.I. TEST (PRINTOUT ATTACHED) ICATE THE NUMBER OF BREATH TESTS IN THE FOLLOWN NOT INCLUDE SELF-ADMINISTERED TESTS) FUSALS (004) (00509) MAY NEW PARTS AND DESCRIBE ANY ALTERATION OR MODIFICATION THAT WAS MADE OTHER SIDE IF NECESSARY).	USED PER MAINTENANCE REPORT) It be within ±5% of the standard value and must have a spread or a used. (PRINTOUT ATTACHED) ID 0.105% INCLUSIVE ID 0.042% INCLUSIVE TEST 3 - 099 ING RANGES SINCE THE LAST MAINTENANCE REPORT: (.1014)

AN EQUAL OPPORTUNITY/AFFIRMATIVE ACTION EMPLOYER sonitors provided on a nondecimalary basis



CERTIFICATE OF ANALYSIS

Certified Alcohol Reference Solution for Simulator

Random Samples of Lot Number 13280 of Alcohol Reference Solution for Simulator were analyzed by gas chromatography on October 18, 2013, using a Perkin Elmer Gas Chromatograph Autosystem XL S/N: 610N9030209, and found to contain 0.1217% (w/vol) ethyl alcohol. The expiration date for this lot number is October 16, 2015 at 11:59 PM.

When used in a calibrated Simulator, operating at 34°C +/- .2°C, this solution will give a breath alcohol analysis instrument reading of 0.100 g/210L +/- 3%.

The alcohol and water used in this solution were free of test interfering substances.

Ted L. Pauley, President GUTH LABORATORIES, INC.

NIST Traceability:

Testing was conducted using Cerilliant Reference Standard lot number FN122211-02 whose values are traceable to NIST.

All balances are calibrated annually by an outside agency using NIST traceable weights. Calibration verification is done prior to each use utilizing NIST traceable weights.



STATE OF MISSOURI

DEPARTMENT OF HEALTH AND SENIOR SERVICES **BREATH ALCOHOL PROGRAM**



PERMIT TYPE II

MICHAEL D MURRILL

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field service and repairs, and operate the following breath analyzer(s):

DATAMASTER, INTOX DMT

for the determination of the alcoholic content of blood from a sample of expired air. Permit issued under the provisions of sections

577.020 through 577.041, RSMo and 306.111 through 306.119 RSMo.				
DATE3/7/2014	wonde			
NUMBER 240065	DIRECTOR OF STATE PUBLIC HEALTH LABORATORY			
	Darl Vasterly			
EXPIRES 3/7/2016	J			
AD 590.0771 (6.10)	DIRECTOR OF DEPARTMENT OF HEALTH AND SENIOR SERVICES			

MO 680-0771 (6-10)

LAB-4 (R6-10)



MURRILL, MICHAEL Operator Permit No 240065

Date Issued 3/7/2014

Date Expires 3/7/2016

Face This Side Down - This Edge In First

BAC DataMaster Evidence Ticket

MISSOURI STATE HIGHWAY PATROL DAC DATAMASTER SERIAL NUMBER 204073 83739714

ARREST TIME: 08:00 SUBJECT NAME: m/D/m DOB: 01/01/71 SEX# M STATE/D.L.: h0/123456789 PRESTING OFFICER: NZDZN OFFICER 1.D.: 649 TESTING OFFICER: 州。加州 OFFICER L.D.: 649 PERMIT HUMBER: 240865 EXPIRATION DATE: 03/07/16 MISCELLANEOUS DATA:

-- BREATH ANALYSIS ---

BLANK TECO . 868 00156 THTERISH STANDARD VERIFIED 98456 RADIO INTERFERENCE

Face This Side Down - This Edge In First

6.24

BAC DataMaster Evidence Ticket

MISSOURT STRIE HIGHWAY FETROL BAC DATAMASTER SERIOL NUMBER 204073 63736.14 88:22

--- DIAGNOSTIC CARCE ----

COMPUTER: PROGRAM (84-07-2969): (IKI) HEATERS. SAMPLE CHIMBERS Sec FLOW DETECTOR: OWENY Flippe MIGH SELECT OF HE DETERMINATIONS 电压有字 FILTERLE UKBY GLOWING CONTRIBUTE THIRT

CHE LERH CLOTE

PRIMIER (ES) 《中華歌語》(1984年,中,中華主義5456709)(中文79時期自由2年5 HY INCOMERS TO MAKE THE ABOUT THE PROPERTY OF DUCE LOOK, GETTY

UH 67

rator Signature TRMS AUD #649

perator Signature 18 M.S. Will #645

Face This Side Down - This Edge In First

BAC DataMaster Evidence Ticket

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL MUMBER 204073 *19*37/38/714

ARKEST TIME: 88:89 SUBJECT MAME: el/D/H 0008: 01/01/71 DEVI N STATE/B.L.: M0/123456769 HERESTIMG OFFICERS MaDam OFFICER L.D.: 649 TESTING OFFICERS A. Turk OFFICER L.D.: 649 PERMIT HUMBER: 248065 EXPIREDION DATE: 03/67/16 MISCELLAMEOUS DATA:

--- BREATH AMELYSIS ---

	BURNK TEST	, ROS	ensit 58
·,	INTERNAL STANDARD	VERIF1E1	66456
	SUBJECT SAMPLE	. Obe	Heli (yd)
)	ELFMR TEST	, tiữlo	68169

Operator Signature 1 AR M. M. M. M. C. 49